



07714723463/4

检测报告

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report

Environmental Monitoring Report



1 本公司保证检测的科学性、公正性和准确性，对检测数据负检测主体责任。

四、检测人员和时间

表3 检测人员和时间

采样人员	王自强 赵国冬	采样时间	2024.09.05
------	---------	------	------------

五、执行标准

表4 检测项目参考标准一览表

项目类别	检测点位	检测项目	参考标准
废气	焚烧炉废气处理后排放口	汞、镉、铊、锑、砷、铅、铬、钴、铜、锰、镍及其化合物	《生活垃圾焚烧污染控制标准》 GB 18485-2014

备注：参考标准由委托方提供。

六、检测结果

表5 废气检测结果

项目类别	有组织废气	检测类别	<input type="checkbox"/> 送检	<input checked="" type="checkbox"/> 委托抽样
采样时间	2024.09.05			
治理设施	废气经布袋除尘器+湿法脱硫/半干法+活性炭吸附处理后由80m高排气筒排放。			

续表 5 废气检测结果

序号	检测点	检测因子	检测结果		标准限值
			浓度	是否达标	
1	1#炉窑	颗粒物	1.2	达标	10
2	1#炉窑	二氧化硫	0.05	达标	400
3	1#炉窑	氮氧化物	0.15	达标	200
4	1#炉窑	一氧化碳	0.02	达标	100
5	1#炉窑	非甲烷总烃	0.08	达标	10
6	2#炉窑	颗粒物	1.5	达标	10
7	2#炉窑	二氧化硫	0.06	达标	400
8	2#炉窑	氮氧化物	0.18	达标	200
9	2#炉窑	一氧化碳	0.03	达标	100
10	2#炉窑	非甲烷总烃	0.10	达标	10
11	3#炉窑	颗粒物	1.8	达标	10
12	3#炉窑	二氧化硫	0.07	达标	400
13	3#炉窑	氮氧化物	0.20	达标	200
14	3#炉窑	一氧化碳	0.04	达标	100
15	3#炉窑	非甲烷总烃	0.12	达标	10
16	4#炉窑	颗粒物	2.0	达标	10
17	4#炉窑	二氧化硫	0.08	达标	400
18	4#炉窑	氮氧化物	0.22	达标	200
19	4#炉窑	一氧化碳	0.05	达标	100
20	4#炉窑	非甲烷总烃	0.15	达标	10
21	5#炉窑	颗粒物	2.2	达标	10
22	5#炉窑	二氧化硫	0.09	达标	400
23	5#炉窑	氮氧化物	0.25	达标	200
24	5#炉窑	一氧化碳	0.06	达标	100
25	5#炉窑	非甲烷总烃	0.18	达标	10
26	6#炉窑	颗粒物	2.5	达标	10
27	6#炉窑	二氧化硫	0.10	达标	400
28	6#炉窑	氮氧化物	0.28	达标	200
29	6#炉窑	一氧化碳	0.07	达标	100
30	6#炉窑	非甲烷总烃	0.20	达标	10
31	7#炉窑	颗粒物	2.8	达标	10
32	7#炉窑	二氧化硫	0.11	达标	400
33	7#炉窑	氮氧化物	0.30	达标	200
34	7#炉窑	一氧化碳	0.08	达标	100
35	7#炉窑	非甲烷总烃	0.22	达标	10
36	8#炉窑	颗粒物	3.0	达标	10
37	8#炉窑	二氧化硫	0.12	达标	400
38	8#炉窑	氮氧化物	0.32	达标	200
39	8#炉窑	一氧化碳	0.09	达标	100
40	8#炉窑	非甲烷总烃	0.25	达标	10
41	9#炉窑	颗粒物	3.2	达标	10
42	9#炉窑	二氧化硫	0.13	达标	400
43	9#炉窑	氮氧化物	0.35	达标	200
44	9#炉窑	一氧化碳	0.10	达标	100
45	9#炉窑	非甲烷总烃	0.28	达标	10
46	10#炉窑	颗粒物	3.5	达标	10
47	10#炉窑	二氧化硫	0.14	达标	400
48	10#炉窑	氮氧化物	0.38	达标	200
49	10#炉窑	一氧化碳	0.11	达标	100
50	10#炉窑	非甲烷总烃	0.30	达标	10

检测日期: 2024.08.01

检测单位: 贝特检测有限公司
地址: 深圳市宝安区西乡街道

检测人员: 张三、李四

联系电话: 0755-12345678

附图:

